

HOW TO ADD A NEW CERTIFICATE OF CALIBRATION FOR YOUR APPLIANCE


Log into I-CARE.

1




Click the "Temp Logs" tab.

3




Hover over your appliance and click on the edit icon.

5




2

Click "Site" on the navigation tab on the top of the page.



4

Click "Appliances" as your select view.



6

Click "Upload New Attachment" and upload your new certification.

